		CATION SECRET/COLL		The second secon	250					
	Approved Fo	ERITERS 120 BIOLOGICA	FIPENT IAL5	7R 02P0007200 .12-6	25X					
		ORMATION	REPORT	CD NO.	11/833					
COUNTRY	Germany (Russian 2	(one)		DATE DISTR.	27 February 19					
Subject	Personnel Figures Repair Shops	for Railroad		NO. OF PAGES	2					
PLACE ACQUIRED		Decument No No Change in Class. [Declass Red	01 +	NO. OF ENCLS.						
DATE OF 1info.		Class. Changed Ter	TS S (C) 25X	1 SUPPLEMENT 1 REPORT NO.						
MIND DECEMBER OF ALEXA	DELITATION (USA) CONTROL APPEARING THE CONTROL OF T	ATTOTAL CONTROL SPICING ACT C SUB CONTROL SUB CONTROL SUBTRACT SUB	THIS IS UNEVA	LUATED INFORMATION OF THE PROPERTY OF THE PROP						
25X1 ¹ 。	The following info	ormation on the per	sonnel strength		road repair cember 1950:					
	Repair shops for locomotives		Personnel strength *							
	Halle		2,190							
	Meiningen Schlauroth		2 ,653 429							
	Stendal		2 ₂ 650							
	Repair shops for rolling stock		Personnel strength *							
	Berlin-Tarsch	amerstrasse		1,415						
	Delitzsch			09ناو 1						
	Dessau		1,109 2,018 1,1:00							
	Dresden									
	berswalde									
	Cotha Grunewald			1,822 558						
	Jena Jena			3,073						
	l'agdeburg			2,070						
	alchin			26lı						
	Potsdær.			777						
	Schoeneweide			1,343						
	Repair shops for I	locomotives and	Pers	onnel strength						
	Dlankenburg			613						
	Prandenburg-	lest	1,999							
	Chernitz		3,955							
	Cottbus			1,712						
	Halberstadt Leipzig Tempelhof		1,073 3,430 1,331							
						Tittenberge Zwickau		1,127 3,495		
						Telecommunications service		460 **		
		Commission of the Commission o	ACONOMÍA DE PICARROCO SISTEMA MERISANTARION		400 308					
	genislamenssallenings.	CLASSIF	CATION SECREDNE	HDENTIAL	CILLA CILY					
(meaning	Land Mark	Mixroin:	ITION I	1 1	1 7 7					

Approved 501 Release 2006/02/28: CIA-RDP82-00457R007000720012-6

CENTRAL INTELLIGENCE AGENCY

25X1

25X1		
	Comment. The	figures on the personnel assigned to the individual rail-
	road repair installat	ions are mean values representing the status of July through
	September 1950。	
25X1 _{25X1}	** Comment.	confirmed previous informa-
	tion on the existence	of 25 railroad repair shops and supplemented it regarding
	the personnel strengt	of 25 railroad repair shops and supplemented it regarding the of these installations. The newly
	established auxiliary	railroad shop in Euldenstein was not included in this
	tabulation.	4

SECRET-CONTROL/US-0 FROTAGE ONLY